

EQUAL PRESSURE "E" TYPE MIXERS



PART NO.	FITS HANDLE	GAS	WELDING TIPS	HEATING TIPS	BRAZING TIPS	FLAME CLEANING TIPS
M105	105	Oxy-acetylene	1059 (00, 01, 03, 05, 06) + tube 10593	-	-	-
M105	105	Oxy-propane	-	-	1059N (00, 01, 03, 05, 06) + tube 10593	-
B-15-3	15-3, 15-4, 15-4GB	Oxy-acetylene	5090 tips: 0, 1, 2, 3, 4, 5, 6, 7, 8	1390-HA (+tube D-50-C)	-	-
B-15-3	15-3, 15-4, 15-4GB	Oxy-acetylene	1390 tips: 00, 0, 1, 2, 3, 4, 5, 6, 7, 8	1390-HA (+tube D-50-C)	-	-
B-15-3	15-3, 15-4, 15-4GB	Oxy-acetylene	0090 tips: 1,3, 5, 6, 8 (+ tip holder TH-119)	1390-HA (+tube D-50-C)	-	-
E-43	43-2, 263, 543	Oxy-acetylene	23A90 tips 0,1,3,5,6,8,9,10	J-63 tips 1,2	-	-
E-43	43-2, 263, 543	Oxy-acetylene	0090 tips 1,3,5,6,8 (+adapter 4301-11+TH-119)	1390-HA (+tube 8593)	-	-
E-43	43-2, 263, 543	Oxy-acetylene	1390 tips 00,0,1,3,5,6,8,9,10 (+tube 8593)	-	-	-
E-43	43-2, 263, 543	Oxy-propane	-	-	1390-N tips 2,3,4,5,6,7,8,9,10 (+ tube 8593)	-
E-43	43-2, 263, 543	Oxy-propane	-	-	0090-N tips 2,4,6,8 (+adapter 4301-11 +TH-119)	-
E2-43	43-2, 263, 543	Oxy-acetylene	23A90 tips 13,15	J-63 tips 3,4	-	RBA-43 tips 2,4,6 (+tube 2393+2357-3)
E3-43	43-2, 263, 543	Oxy-acetylene		J-143-5	-	-
D-85	85	Oxy-acetylene	23A90 tips 0,1,3,5,6,8,9,10	J-63-tips 1,2	-	-
D-85	85	Oxy-acetylene	0090 tips 1,3,5,6,8, (+adapter 4301-11+TH-119)	1390-HA (+tube 8593)	-	-
D-85	85	Oxy-acetylene	1390 tips 00,0,1,3,5,6,8,9,10 (+tube 8593)	-	-	-
H-19-2E	19-6, 50-9	Oxy-acetylene	5090 tips 0,1,3,5,6,8,9,10	J-63-tips 1,2 (+adapter 1901-11)	-	-
H-19-2E	19-6, 50-9	Oxy-acetylene	0090 tips 1,3,5,6,8 (+tip holder TH-119)	1390-HA (+tube 8593)	-	-
H-19-2E	19-6, 50-9	Oxy-acetylene	1390 tips 00,0,1,3,5,6,8,9,10 (+tube D-50-C)	-	-	-
H-19-2E	19-6, 50-9	Oxy-acetylene	0090 tips 1,3,5,6,8	-	-	-
F-43	43-2, 263, 543	Oxy-propane	-	2290-H tips 1,2,3,4,5 (+ tube 2393+2357-3)	2290-N tips 13,15,20,30,80 (+tube 2393+2357-3)	RBP-43 tips 2,4,6 (+tube 2393+2357-3)